DATE: 10th November 2026

FSCA/FSN REF.: MDS-26-06177

URGENT: FIELD SAFETY NOTICE (FSN)
BD Connecta™ Stopcock

For Attention of: Clinical Personnel, Risk Managers, Purchasing Managers

Action Being Taken by the Manufacturer			
☒	Product removal	☐	On-site device modification/inspection
☐	Software upgrade	☐	IFU or labelling change
☐	Advisory	☐	Other
Provide further details of the action(s) identified		*N/A*	

Information on Affected Devices

Manufacturers SRN: CH-MF-000026539

Product name	Product Code (REF)	UDI-DI	Package UDI-DI	Lot number / Serial number	Expiry Date
BD Connecta™ Stopcock with Extension Tube - 16 cm (White)	394995	00382903949953	30382903949954	Refer to webpage: https://bdx.my.site.com/CC360/s/impactedproducts?language=en_US&rn=MMS-26-06177%20GLOBAL	
BD Connecta™ Stopcock with Extension Tube - 16 cm (Blue)	394997	00382903949977	30382903949978		

Reason for Field Safety Corrective Action (FSCA)

Description of the product problem

Based on customer feedback, BD has identified that specific lot numbers of the BD Connecta™ Stopcock product codes listed above (refer to the webpage to identify the affected lot numbers) may have been manufactured with an inadequate amount of solvent and may result in separation of the tubing from the male luer component, refer to image 1.

All other active Connecta™ Stopcock product codes (REF) are not affected by this issue.

Product was distributed between March 2025 and September 2026.




Image 1: Location of tubing to luer separation

Hazard giving rise to the FSCA

Separation of the Connecta™ Stopcock extension tubing may occur during use, resulting in a compromised fluid pathway. This may result in leakage with the potential consequences including under-infusion or disruption of prescribed therapy, exposure to potentially hazardous fluids, infection or air embolism. The separation may be apparent upon initiation of infusion, or during standard patient care at which point the healthcare professional can promptly discontinue use and replace the affected stopcock extension set.

To date, 58 complaints worldwide have been received for this issue. Serious incidents have been filed as appropriate, following procedure.

Other information relevant to FSCA

- BD has identified the root cause and will implement appropriate corrective and preventative measures to prevent recurrence.
- BD will provide replacement upon receipt of a completed customer response form.

Please note: Product codes (REF) 394995 and 394997 were previously included in Field Safety Notice MDS-26-06018 (May 2026), which addressed a separate issue relating to over-threading at Port C of the BD Connecta™ Stopcock. The current Field Safety Corrective Action, MDS-26-06177, relates to specific lots of these product codes that may have been manufactured with an inadequate amount of solvent, potentially resulting in separation of the extension tubing from the male luer component. Customers should follow the actions specified in this Field Safety Notice for the affected lots.

Device Type(s)

The BD Connecta™ Stopcock is a stopcock with two ports and a rotating lever to control fluid direction through the device.



BD Connecta™ Stopcock with Extension Tube - 16 cm (White), product code (REF) 394995



BD Connecta™ Stopcock with Extension Tube - 16 cm (Blue), product code (REF) 394997

Primary clinical purpose of devices(s)

BD Connecta™ Stopcocks are used to administer fluids or medication through one or two different ports via an IV cannula or extension tube. The ports can be used to sample blood or for hemodynamic monitoring. When used with lipid nutritional products, the Connecta™ device can be used for up to 24 hours. The BD Connecta™ Stopcock is intended to be used by healthcare professionals who are experienced in infusion therapy.

DATE: 10th November 2026

FSCA/FSN REF.: MDS-26-06177

General Information

FSN type: NEW

For updated FSN, reference number and date of previous FSN: N/A

For updated FSN, key new information as follows: N/A

Further advice or information already expected in follow up FSN? No

Type of Action to mitigate the risk							
Action To Be Taken by the User							
☒	Identify Device	☒	Quarantine Device	☐	Cease Use	☐	Return Device
☒	Destroy Device	☐	On-site device modification/inspection	☐	Follow patient management recommendation's		
☐	Take note of amendment/reinforcement of Instructions for Use (IFU)			☐	Other		
Provide further details of the action(s) identified				Make a note of the lot numbers and destroy all affected units			

Particular considerations for:

- Cease use of the Affected Product listed above.
  - The Affected product codes and lot numbers can also be found on the webpage: https://bdx.my.site.com/CC360/s/impactedproducts?language=en_US&rn=MMS-26-06177%20GLOBAL
- If the product is currently in use, replace immediately with unaffected product.
  - If the product is already in use and you are unable to determine if it is within scope as the packaging or other records are not available, it is recommended to replace with unaffected product.
- If affected product has already been used and is no longer in situ, no patient follow up activities are required.

Note: During the investigation of complaints for this issue, it was reported there was some use with power injection. Clinical users are reminded of the Warning in the Instructions for Use:

DO NOT use with power injectors. Doing so may result in leakage and/or failure of the device.

Is follow-up of patients or review of patients' previous results recommended? No

Provide further details of patient-level follow-up if required or a justification why none is required: If affected product has already been used and is no longer *in situ*, no patient follow up activities are required.

Is customer Reply Required: Yes

DATE: 10th November 2026

FSCA/FSN REF.: MDS-26-06177

Complete the form in its entirety and return the Customer Response Form even if you no longer have any inventory remaining in your facility by **30th November 2026**.

Action To Be Taken by the Distributor							
☒	Identify Device	☒	Quarantine Device	☒	Cease distribution	☐	Return Device
☒	Destroy Device	☐	On-site device modification/inspection	☐	Take note of amendment/reinforcement of Instructions for Use (IFU)		
☒	Identify the facilities where you have distributed affected product and notify them immediately of this notice.			☒	Have your customers complete and return the Customer Response form to your organisation for reconciliation purposes		
☒	Complete and return the Customer Response Form following completion of your reconciliation activities			☐	Other		
Provide further details of the action(s) identified				Make a note of the lot numbers and destroy all affected units			

	End User with Inventory	**End User with ZERO inventory**	**Where to send completed form**
Purchased/distributed **directly** from BD	Complete the form in its entirety and ensure that all recommended actions have been implemented as required	Complete the form in its entirety and retain a copy of this notification for your records	BDFieldactions@bd.com
Purchased/distributed from a **distributor/3rd party**	Complete the form in its entirety and ensure that all recommended actions have been implemented as required	Complete the form in its entirety and retain a copy of this notification for your records	Return the form to your distributor

Contact details of local representative: If you have any questions about this, please contact your local BD representative or the local BD office or e-mail BDFieldactions@bd.com

Transmission of this Field Safety Notice

- This notice needs to be passed on to all those who need to be aware within your organisation or to any organisation where the potentially affected devices have been transferred
- Transfer this notice to other organisations on which this action has an impact.
- Maintain awareness of this notice and resulting action for an appropriate period to ensure effectiveness of the corrective action.
- Report all device-related incidents to the manufacturer, distributor or local representative, and the national Competent Authority if appropriate, as this provides important feedback

The competent (Regulatory) Authority of your country has been informed about this communication to customers

Appendix 1 - Product Code / Lot number Identification



Image 2: Representative image to show location of the product code (REF) and lot number.