

PRODUCT UPDATE

AMVC1792-013 | AMVC1792-070 | AMVC1792-156 | AMAC1401-001

I am pleased to let you know that these products are once again available.

We have identified the root cause of the issue with the above circuits resulting in FSN BiPAP Tubing CF-1573 and made a small amendment to the circuit that eliminates the issue.

There is no change to the function or ability of the circuit to connect, there is one noticeable aesthetic change.



The over moulded connector, fig 1, has been replaced with an inserted connector, fig 2, with the same connection dimensions.

The circuit will function in exactly the same way and is available for order and delivery under our normal 3-5 day service.

I apologise once again for any inconvenience caused and look forward to continuing to support you in providing the highest standards of care for your patients.



eakinrespiratory.com

Manufactured by
Armstrong Medical Limited
Wattstown Business Park,
Newbridge Road,
Coleraine, BT52 1BS,
Northern Ireland.
T +44 (0) 28 7035 6029
coleraine@eakinhealthcare.com